

Fig. 1 *has been replaced*






Fig. 2a




BOTTOM VIEW

Fig. 2b




SIDE VIEW

Fig. 2c




PERSPECTIVE VIEW

Fig. 2d

XeF₂ INJECTOR DURING THE ETCHING STEP


002720 584 1718 09614785 074200

Fig. 3a



BOTTOM VIEW


Fig. 3b



SIDE VIEW


0027205847960

Fig. 3c



PERSPECTIVE VIEW

Fig. 3d

X6F₂ INJECTOR DURING THE ETCHING STEP

002720 584 1718 09644785 074200

Fig. 4





Fig. 5



002720" 584 1718